


705290 021125 060

FIG. 1  
PRIOR ART



2/12

FIG. 2A





FIG. 2B




100-2000-0024458610

SILICA STRUCTURE CRACK MONITORING  
CADET et al.  
Serial No. : 09/852,420  
Schnader, Harrison, Segal & Lewis, LLP (215) 751-2000 ref# 1525-00

3/12

FIG. 3



09/852,420 - 1525-00

SILICA STRUCTURE CRACK MONITORING

CADET et al.

Serial No. : 09/852,420

Schnader, Harrison, Segal & Lewis, LLP (215) 751-2000 ref# 1525-00

4/12

106280-02425360

FIG. 4




FIG. 5






FIG. 6



7/12

FIG. 7




09852420-00601

8/12


*FIG. 8a*

CHANNEL 1




*FIG. 8b*

CHANNEL 2



*FIG. 8c*

CHANNEL 3




09852420-082904

SILICA STRUCTURE CRACK MONITORING  
CADET et al.  
Serial No. : 09/852,420  
Schnader, Harrison, Segal & Lewis, LLP (215) 751-2000 ref# 1525-00

9/12

FIG. 9A


WAVEFORM (mV) VS TIME (USED)



ପାତ୍ରବିନ୍ଦୁ ପାତ୍ରବିନ୍ଦୁ

FIG. 9B


WAVEFORM (mV) VS TIME (USED)



SILICA STRUCTURE CRACK MONITORING  
CADET et al.  
Serial No. : 09/852,420  
Schnader, Harrison, Segal & Lewis, LLP (215) 751-2000 ref# 1525-00

10/12

FIG. 10



10/12 00-0245260

## SILICA STRUCTURE CRACK MONITORING


CADET et al.

Serial No. : 09/852,420

Schnader, Harrison, Segal & Lewis, LLP (215) 751-2000 ref# 1525-00

11/12

FIG. 11




Digitized by srujanika@gmail.com

SILICA STRUCTURE CRACK MONITORING  
CADET et al.  
Serial No. : 09/852,420  
Schnader, Harrison, Segal & Lewis, LLP (215) 751-2000 ref# 1525-00

12/12

*FIG. 12*



0985240 088601